

FIELD BUS



**Danger**

High  
Voltage

# UNIPRO<sup>M</sup>


I/O Module 1

I/O Module 2

Scan here for further  
product information



FUSE  
1.6A 250VT



SUPPLY		SENSOR		
V+	GND	D+	D-	V+
				GND

- STATUS LED
- DIG. OUT DRY ○
  - DIG. OUT SSR ○
  - ERROR ○
  - COMMS ○
  - HEARTBEAT ○

DIGITAL O/P	
DRY	SSR
N.C.	N.O.
COM	C1
	C2

PTU



EARTHING STUD (M5)